

OUT52105

SECRET 182002Z

25X1

1. CAMERA B 8 WAS USED IN MISSION 3752 FLOWN ON 16 OCTOBER 1963 OCT 13 23 00Z

1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

21 OCT 1963

2. ORIGINAL NEGATIVE:

A. THE RESOLUTION IS GOOD AND THE EXPOSURE IS ADEQUATE.

B. 9R SIDE: A CREASE ALONG THE INBOARD EDGE IS NOTED ON FRAMES 590 THROUGH 599 (END OF ROLL) AND CONTINUES ON THE TAIL IDENTIFICATION LEADER. A MANUFACTURER'S SPLICE IS PRESENT THROUGH FRAMES 37 AND 493, AND ASSOCIATED WITH THESE SPLICES ARE SMALL CREASES AND STATIC TRACES ON FRAMES 36, 37, 40, 493, 494, 496, 497 AND 498. IMPROPER DRYING RESULTED IN FRAMES 2094 THROUGH 2099 BEING STAINED AND TACKY. A CHEMICAL STAIN 4.0" BY 0.75" IS NOTED ON FRAME 467. A HEAVIER THAN USUAL PLUS DENSITY AREA 0.2" WIDE, CAUSED BY A REFLECTION FROM THE FORMAT, OCCURS THROUGHOUT THIS MISSION.

C. 9L SIDE: CHEMICAL STAINS AND EMULSION LIFTS OCCUR ON FRAMES 1237 AND 1238 WITH ONLY CHEMICAL STAINS ON FRAMES 1607 AND 1774. OCCASIONAL BLISTERS AND/OR PINHOLES OCCUR THROUGHOUT THIS MISSION.

D. BOTH SIDES: THE METERING IS SLIGHTLY ERRATIC WITH NO OVERLAPPING FORMATS NOTED. PROCESSING STREAKS ARE PRESENT THROUGHOUT THIS MISSION. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED ON THIS MISSION OTHER THAN THOSE MENTIONED

HFS
CJS
CIS
FIS
JAL
Glace (File)

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

ABOVE.

3. POSITIVE:

A. PI SUITABILITY IS FAIR DUE TO A GRAINY, HIGH CONTRAST
PRINT.

B. PRINTING AND PROCESSING ARE FAIR.

C. CLCUDS OBSCURE APPROXIMATELY 30 PERCENT OF THIS MISSION.

S E C R E T

END OF MESSAGE

1